


Mounting information for concentricity gauges




measuring internal diameters





The slide can be rotated through 90° allowing rapid clearance and positioning for changing parts



The slide is adjusted with a a screw. The two positioning holes allow for an extended working area.